These Bullhead Safety® Eyewear styles have

PASSED ARC FLASH TESTING

to 35 cal/cm² without ignition





















These products have met minimum requirements for Arc Flash Testing and may be suitable for complying to ASTM F1506, NFPA 70E and CSA Z462 workplace electrical safety requirements.

WHAT is Arc Flash Testing?

An arc flash is an electric arc explosion from an arcing fault which produces both radiant and convective heat with the potential to ignite clothing and burn workers.

The purpose of the test is to observe the response characteristics of safety glasses when exposed to an open-air electric arc. Arc flash testing is performed to determine a product or material's response to an electrical arc event by establishing an arc rating.

WHY Arc Flash Tested?

The most serious injuries typically occur when clothing ignites – arc flash testing is performed to ensure clothing will not ignite when faced with an arc flash.

Matching the PPE to the hazard most often results in no injury to the worker since arc hazard assessment is typically very conservative.

Contact your Global Glove sales representative today to purchase Arc Flash Tested glasses from Bullhead Safety® Eyewear.

WHO needs Arc Rating?

Arc flash testing is relevant for any worker potentially exposed to an electric arc generating a heat flux of >2 cal/cm².

Anyone with exposure to electrical hazards must have arc rated PPE available, as mandated by OSHA.

13915 Radium St NW Ramsey, MN 55303

763-450-0110 Sales@BullheadSafety.com

BullheadSafety.com

